

EARTH TECH DAILY SAFETY MEETING

DATE: 4/11/05	TIME: 0830	CLIENT: US EPA REG 5
SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI		JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

PROTECTIVE CLOTHING/EQUIPMENT: Level C, safety glasses, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose) ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety, truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT:

OTHER: - Report any unsafe jobsite conditions ASAP!!

- Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Steve Butler
 Brad Henrich
 Jason Coy
 Craig J. Reberschke
 Steve R. Altmann
 Brett Hodgson
 Sherida Brown

[Signatures]
 Jason Coy
 Steve R. Altmann
 Brett Hodgson
 Sherida Brown










US EPA RECORDS CENTER REGION 5



467477

Meeting Conducted By:

[Signature]

EARTH TECH DAILY SAFETY MEETING		
DATE: 4/12/05	TIME: 0800	CLIENT: US EPA REG 5
SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI		JOB #: 84735.01
SAFETY TOPICS PRESENTED		
Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task		
PROTECTIVE CLOTHING/EQUIPMENT: Level C, safety glasses, index gloves, over gloves and hearing protection as needed		
CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose)ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.		
PHYSICAL HAZARDS: slips, trips & falls, equipment safety, truck & roll-off unloading/ loading & spotting, biological hazards, weather		
HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000		
18101 Oakwood Blvd, #1, Dearborn, Michigan 48124		
*Report any near misses & all accidents to your supervisor immediately!!!		
SPECIAL EQUIPMENT:		
OTHER: - Report any unsafe jobsite conditions ASAP!!		
- Don't discuss this project with <u>anyone</u> , refer them to the EPA OSC.		
ATTENDEES:		
- Print	- Sign	
Craig Peltuska		
Brod Horrich		
Jason Coy		
Steve R. Adelman		
Steve Pankus		
Don Wynn		
Brett Hodgson		
Shenita Brown		
Meeting Conducted By: 		

EARTH TECH DAILY SAFETY MEETING

DATE: 4/13/05

TIME: 0800

CLIENT: US EPA REG 5

SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI

JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brad Hendrick

Steve R. Adelman

Stew Parker

Craig Reischke

Jason Coy

Dave Wagner

BRETT HODGSON

LORI Ash

Shenita Brown

Ted LeMura

Eric M. Mendenhall

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

Meeting Conducted By:

[Signature]

* cont soils
excav &
dust control

- pressure
wash ahead
of excav
- hand wash
station

* break times
1030, 1300, 1630

* mark three
& initial the
change on
all docs

EARTH TECH DAILY SAFETY MEETING

DATE: 4/14/05	TIME: 0800	CLIENT: US EPA REG 5
SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI		JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

Sign

Steve R. Adelman

Brad Herrick

Craig Rebuschke

Jason Gay

Steve Pickett

Ted LeMay

LORI ASH

ERIK MARTINSON

Dave Wagner

Sherita Brown

BRETT HOPKINSON

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

Meeting Conducted By:

[Signature]

*Soils excav
*dust control
at all times
*Take your
time
*End of
day work
*Safety
Incentive
T-shirt

EARTH TECH DAILY SAFETY MEETING

DATE: 4/15/05 TIME: 0800 CLIENT: US EPA REG 5
 SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed, Safety vests

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brad Hendrick
 Steve R. Adelmann
 Sherita Brown
 Craig Belischnie
 Steve Baker
 Joann G
 Lori Ash
 Erika Martinson
 Ted Li Mun
 BRETT HODGSON

[Signatures]
 Steve R. Adelmann
 Sherita Brown
 Craig Belischnie
 Steve Baker
 Joann G
 Lori Ash
 Erika Martinson
 Ted Li Mun
 BRETT HODGSON

Meeting Conducted By:

[Signature]

* Cont
 Soils excav
 & loading rail
 dust control
 *Free liquids
 *1730

EARTH TECH DAILY SAFETY MEETING

DATE: 4/16/05

TIME: 0800

CLIENT: US EPA REG 5

SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI

JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brod Hennrich
Steve R. Adelman
Shelita Brown
Craig Nebischke
Jason Coy
Steve Baker
Lori Ash
ERIK MARTINSON

[Signatures]

Meeting Conducted By:

[Signature]

*Cont soils
excav, area of
dust control
*site inspt
*near miss

*evals

EARTH TECH DAILY SAFETY MEETING

DATE: 4/18/05 TIME: 0800 CLIENT: US EPA REG 5
 SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone half face

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

BRETT HODGSON

Cynthia Rebuschko

Steve Hester

Brian Hester

Jason Loy

Steve Adelman

Erik Martinson

Lori Ash

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

Meeting Conducted By:

[Signature]

* Soils excavo
in area of,
dust C to
sunny, fence
+ fabric

* Fuel dip

hay bales

EARTH TECH DAILY SAFETY MEETING

DATE: 4/19/05 TIME: 0800 CLIENT: US EPA REG 5
 SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

BRETT HONGSON

Steve Parker

Craig Relisnick

Jeffrey Goy

Steve R. Heilmann

LORI ASH

Brett Hongson

Steve Parker

Craig Relisnick

Jeffrey Goy

Steve R. Heilmann

Lori Ash

Meeting Conducted By:

[Signature]



*Soils exca area 02
*D C

*Heat stress baseline monitoring
*End of day frost

EARTH TECH DAILY SAFETY MEETING

DATE: 4/20/05

TIME: 0800

CLIENT: US EPA REG 5

SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI

JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

*Report any near misses & all accidents to your supervisor immediately!!!

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brad Hendrick

Jason Gay

Chris Cringhousake

Steve Parker

Sherrita Brown

Lori Ash

Steve R. Alderman

Brett Hodgson

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

Meeting Conducted By:

[Signature]



*area of
Soils excav
DC

Severe
weather
Silt fence
roll offs

EARTH TECH DAILY SAFETY MEETING

DATE: 4/21/05

TIME: 0800

CLIENT: US EPA REG 5

SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI

JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

*Report any near misses & all accidents to your supervisor immediately!!!

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Craig Pelischke

Steve R. Adelmann

Steve Parker

Brad Hendrich

Jason G

Shenita Brown

Lori Ash

[Signatures]

Meeting Conducted By:

[Signature]

* Cont Soils
excl from
area 01
* DC
* cold stress

EARTH TECH DAILY SAFETY MEETING

DATE: 4/22/05

TIME: 0900

CLIENT: US EPA REG 5

SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI

JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed, safety

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

*Report any near misses & all accidents to your supervisor immediately!!!

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Jason Loy

Craig Pelissier

Steve Parker

Star R. Adelman

Brian Hendrick

Cori Ash

~~Steve Parker~~

SP Sherita Brown

Jason Loy

Craig Pelissier

Steve Parker

Star R. Adelman

Brian Hendrick

Cori Ash

~~Steve Parker~~

SP Sherita Brown

Meeting Conducted By:



+Cont Soils

ETGV area 02

*DC

*weather

*Hertz

EARTH TECH DAILY SAFETY MEETING

DATE: 4/23/05

TIME: 0800

CLIENT: US EPA REG 5

SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI

JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Craig Rebeschke
Steve R. Adelmann
Jason Gay
Steve Parker
Shenita Brown
Lori Ash
Brad Henkel

[Signatures]

Meeting Conducted By:



*Cont Soils
exclav area
02 Brad
*DC Craig
*Stone over
fabric in
area 01

EARTH TECH DAILY SAFETY MEETING

DATE: 4/25/05

TIME: 0900

CLIENT: US EPA REG 5

SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI

JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task

listen to others if there is a concern in exclusion zone

PROTECTIVE CLOTHING/EQUIPMENT: Level C, respirator, index gloves, over gloves and hearing protection as needed, safety glasses

CHEMICAL HAZARDS: Asbestos in soils (dust control, water hose), ET does daily personnel air monitoring, **ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brad Hendrick

Jason Gay

Steve Parker

Craig Delisenske

Lori Ash

Sherita Brown

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

Meeting Conducted By:

[Signature]

*Soils excav area 02
*DC

*Stone in area 01

*Great wk

*T-shirt
Safety Award

Hertz-Excar

*hay, grass seed

EARTH TECH DAILY SAFETY MEETING

DATE: 4/26/05 TIME: 0800 CLIENT: US EPA REG 5
 SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task ***listen to others if there is a concern in exclusion zone***

PROTECTIVE CLOTHING/EQUIPMENT: Level C/half face respirator, safety glasses, n-dex gloves, leather or cotton gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control), ET does personnel air monitoring (as per "Neg Exp Asmt memo"), *ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Craig Belischnie
 Jason
 Stew Pappas
 Steve P. Helmann
 Brad Henrich
 Lori Ash

[Signatures]

Meeting Conducted By:

[Signature]

EARTH TECH DAILY SAFETY MEETING

DATE: 4/27/05 TIME: 0700 CLIENT: US EPA REG 5
 SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task ***listen to others if there is a concern in exclusion zone***

PROTECTIVE CLOTHING/EQUIPMENT: Level C/half face respirator, safety glasses, n-dex gloves, leather or cotton gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control), ET does personnel air monitoring (as per "Neg Exp Asmt memo"), *ERT does the site perimeter air monitoring.
 PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brad Hargis

Craig Delisio

Stew Parker

LORI ASH

Jason Co

Steve A. Adelman

Shenita Brown

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

Meeting Conducted By:

[Signature]



*Soils excav
 in areas 02
 & 03
 *DC

*Stone raking
 in area 01

*poly when
 we pass over
 other areas

EARTH TECH DAILY SAFETY MEETING

DATE: 0700 TIME: 4/28/05 CLIENT: US EPA REG 5
 SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task ***listen to others if there is a concern in exclusion zone***

PROTECTIVE CLOTHING/EQUIPMENT: Level C/half face respirator, safety glasses, n-dex gloves, leather or cotton gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control), ET does personnel air monitoring (as per "Neg Exp Asmt memo"), *ERT does the site perimeter air monitoring
 PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/loading & spotting, biological hazards, weather, overhead electric
 HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Stew Parker
 Cyga Petersen
 J. R. Koon
 Brad Henschel
 Lori Ash
 Jason Coy
 Sherrin Brown

[Signatures]
 Lori Ash
 Jason Coy
 Sherrin Brown

Meeting Conducted By: *[Signature]*

*cont Soils
 excav-area 03
 *DC
 *cleaning drop
 *Soils
 *filter fabric
 area 02

*overhead
 power line
 *underground
 lines/gas!

EARTH TECH DAILY SAFETY MEETING

DATE: 4/29/05 TIME: 0700 CLIENT: US EPA REG 5
 SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task ***listen to others if there is a concern in exclusion zone***

PROTECTIVE CLOTHING/EQUIPMENT: Level C/half face respirator, safety glasses, n-dex gloves, leather or cotton gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control), ET does personnel air monitoring (as per "Neg Exp Asmt memo"), *ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brad Henrik
 Craig Delischi
 Jason G
 Steve P
 Steve R-Adelmann
 Sherita Brown
 Lori Ash

[Signatures]
 J. Smith
 J. Smith
 J. Smith
 J. Smith
 J. Smith
 J. Smith
 J. Smith

Meeting Conducted By:

[Signature]

*Complete area 03 soils excav, lay fabric
 *DC

*Curbs, walls wash down

*Pers Air monitoring

*N-papers

EARTH TECH DAILY SAFETY MEETING

DATE: 4/30/05	TIME: 0800	CLIENT: US EPA REG 5
SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI		JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task ***listen to others if there is a concern in exclusion zone***

PROTECTIVE CLOTHING/EQUIPMENT: Level C/half face respirator, safety glasses, n-dex gloves, leather or cotton gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control), ET does personnel air monitoring (as per "Neg Exp Asmt memo"), *ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brad Henrich
Craig Richville
Steve Parker
Stan R. Adelman

[Signatures]

Meeting Conducted By:

[Signature]

EARTH TECH



* Decon equip "Level C"
* Topsoil "D"

EARTH TECH DAILY SAFETY MEETING

DATE: 5/02/05

TIME: 0800

CLIENT: US EPA REG 5

SPECIFIC LOCATION: N-Forcer Site, Dearborn, MI

JOB #: 84735.01

SAFETY TOPICS PRESENTED

Inspect equipment & tools before use, then operate equipment & tools properly, use the correct PPE for the assigned task ***listen to others if there is a concern in exclusion zone***

PROTECTIVE CLOTHING/EQUIPMENT: ^{cup}Level C half face respirator, safety glasses, n-dex gloves, leather or cotton gloves and hearing protection as needed

CHEMICAL HAZARDS: Asbestos in soils (dust control), ET does personnel air monitoring (as per "Neg Exp Asmt memo"), *ERT does the site perimeter air monitoring.

PHYSICAL HAZARDS: slips, trips & falls, equipment safety (wear vests), truck & roll-off unloading/ loading & spotting, biological hazards, weather

HOSPITAL/CLINIC: Oakwood Hospital PH # 313-593-7000

18101 Oakwood Blvd, #1, Dearborn, Michigan 48124

***Report any near misses & all accidents to your supervisor immediately!!!**

SPECIAL EQUIPMENT: HEPA vac when exiting decon

OTHER: - Report any unsafe jobsite conditions ASAP!!

****Don't discuss this project with anyone, refer them to the EPA OSC.

ATTENDEES:

- Print

- Sign

Brad Henrich

Jason Ly

Craig Reichenbe

Stew Parker

Lori Ash

Star A. Williams

Shenita Brown

[Signature]

[Signature]

[Signature]

[Signature]

[Signature]

Meeting Conducted By:

[Signature]

EARTH TECH

